

MAY 1, 2007

Scott Home Inspection, LLC



George Scott, *Owner-Inspector*

Contact Info:

970-532-2424

720-979-4960

george@scotthomeinspection.com

Visit our website!

www.scotthomeinspection.com

Resources On-Line:

- [Services](#)
- [Sample Report](#)
- [Inspection Fees](#)
- [Schedule Availability](#)

Home-Tips On-Line:

[Five quick-tips to quickly recognize serious Structural problems](#)

[Radon - the 6 most frequently asked questions](#)


[Sump Pumps - Tips and Troubles](#)

Inspection Picture of the Month:

Air Conditioner Jungle It's that time of year again, to get the AC fired up and running. Can your outside AC unit breathe, or is a jungle growing around it?



This unit might not operate very efficiently...if the growth around the outdoor unit is excessive, the air flow into the unit can be severely obstructed, and the unit will not function well. The compressor relies on adequate air flow, to help with the cooling process.



Most AC units pull air in from the sides of the unit, and discharge it out the top fan. Keep the area around the compressor clear of all vines, bushes, and growth, to keep your unit running at peak performance.